

not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

98-16-15 British Aerospace (Operations)

Limited: Amendment 39-10691; Docket No. 98-CE-03-AD.

Applicability: Model B.121 Series 1, 2, and 3 airplanes, all serial numbers, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated in the body of this AD, unless already accomplished.

To prevent structural failure of the main spar web area caused by fatigue cracking or separation of the wing caused by loose nuts at the wing to fuselage main-spar attachment fittings, which could result in loss of control of the airplane, accomplish the following:

(a) Within the next 100 hours time-in-service (TIS) after the effective date of this AD, replace the nuts (with improved design nuts) at the wing to fuselage main-spar attachment fittings in accordance with British Aerospace PUP Mandatory Service Bulletin No. B121/106, dated January 12, 1998.

(b) Upon accumulating 2,000 hours TIS on the main spar or within the next 50 hours TIS after the effective date of this AD, whichever occurs later, install an inspection opening and inspect, using eddy current methods, the area at the main spar web for cracks in accordance with the ACCOMPLISHMENT INSTRUCTIONS section of British Aerospace PUP Mandatory Service Bulletin No. B121/105, dated January 12, 1998.

Note 2: Accomplishing the installation inspection opening and initial eddy current inspection required by this AD in accordance with British Aerospace PUP Mandatory Service Bulletin No. B121/102, Revision No. 1, Issued April 16, 1997, is considered "already accomplished" for the requirements of paragraph (b) of this AD.

(c) Within 800 hours TIS after the initial inspection required by paragraph (b) of this AD, and thereafter at intervals not to exceed 800 hours TIS, reinspect the area of the main spar web as specified in paragraph (b) of this AD.

(d) If any cracks are found during any inspection required by this AD, prior to further flight, accomplish the following:

(1) Obtain a repair or replacement scheme from the manufacturer through the FAA, Small Airplane Directorate, at the address specified in paragraph (f) of this AD; and

(2) Incorporate this scheme and continue to repetitively inspect as required by paragraph (c) of this AD, unless specified differently in the instructions to the repair or replacement scheme.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(f) An alternative method of compliance or adjustment of the initial or repetitive compliance times that provides an equivalent level of safety may be approved by the Manager, Small Airplane Directorate, Aircraft Certification Service, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

(g) Questions or technical information related to British Aerospace PUP Mandatory Service Bulletin No. B121/106, dated January

12, 1998, and British Aerospace PUP Mandatory Service Bulletin No. B121/105, dated January 12, 1998, should be directed to British Aerospace (Operations) Limited, British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland; telephone: (01292) 479888; facsimile: (01292) 479703. This service information may be examined at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri.

(h) The replacements, installation, and inspections required by this AD shall be done in accordance with British Aerospace PUP Mandatory Service Bulletin No. B121/106, dated January 12, 1998, and British Aerospace PUP Mandatory Service Bulletin No. B121/105, dated January 12, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from British Aerospace (Operations) Limited, British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland. Copies may be inspected at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

Note 4: The subject of this AD is addressed in British AD 005-01-98, not dated.

(i) This amendment becomes effective on September 21, 1998.

Issued in Kansas City, Missouri, on July 28, 1998.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-20840 Filed 8-6-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-CE-30-AD; Amendment 39-10692; AD 98-16-16]

RIN 2120-AA64

Airworthiness Directives; Pilatus Aircraft Ltd. Model PC-7 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to certain Pilatus Aircraft Ltd. Model PC-7 airplanes. This AD requires replacing the seal unit on both main landing gear (MLG) legs and the nose landing gear (NLG) leg. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Switzerland. The actions specified by

this AD are intended to prevent MLG or NLG failure caused by deterioration of a MLG or NLG leg seal unit, which could result in damage to the airplane or airplane control problems during takeoff, landing, or taxi operations.

DATES: Effective September 21, 1998.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of September 21, 1998.

ADDRESSES: Service information that applies to this AD may be obtained from Pilatus Aircraft Ltd., Customer Liaison Manager, CH-6371 Stans, Switzerland; telephone: +41 41 619 6233; facsimile: +41 41 610 3351. This information may also be examined at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-30-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Mr. Roman T. Gabrys, Aerospace Engineer, Small Airplane Directorate, Airplane Certification Service, FAA, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone: (816) 426-6934; facsimile: (816) 426-2169.

SUPPLEMENTARY INFORMATION:

Events Leading to the Issuance of This AD

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to certain Pilatus Aircraft Ltd. Model PC-7 airplanes was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on May 29, 1998 (63 FR 29360). The NPRM proposed to require replacing the seal unit on both MLG legs and the NLG leg. Accomplishment of the proposed action as specified in the NPRM would be in accordance with Pilatus Service Bulletin No. 32-018, dated March 6, 1998.

The NPRM was the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Switzerland.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposed rule or the FAA's determination of the cost to the public.

The FAA's Determination

After careful review of all available information related to the subject presented above, the FAA has determined that air safety and the

public interest require the adoption of the rule as proposed except for minor editorial corrections. The FAA has determined that these minor corrections will not change the meaning of the AD and will not add any additional burden upon the public than was already proposed.

Cost Impact

The FAA estimates that 5 airplanes in the U.S. registry will be affected by this AD, that it will take approximately 8 workhours per airplane to accomplish this action, and that the average labor rate is approximately \$60 an hour. Parts cost approximately \$932 per airplane. Based on these figures, the total cost impact of this AD on U.S. operators is estimated to be \$7,060, or \$1,412 per airplane.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

98-16-16 Pilatus Aircraft Ltd.: Amendment 39-10692; Docket No. 98-CE-30-AD.

Applicability: Model PC-7 airplanes, all manufacturer serial numbers (MSN) up to and including MSN 609, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated in the body of this AD, unless already accomplished.

To prevent main landing gear (MLG) or nose landing gear (NLG) failure caused by deterioration of a MLG or NLG leg seal unit, which could result in damage to the airplane or airplane control problems during takeoff, landing, or taxi operations, accomplish the following:

(a) Within the next 100 hours time-in-service after the effective date of this AD, replace the seal unit on both MLG legs and the NLG leg in accordance with the ACCOMPLISHMENT INSTRUCTIONS section of Pilatus Service Bulletin No. 32-018, dated March 6, 1998.

(b) As of the effective date of this AD, no person may install, on an affected airplane, a MLG leg or NLG leg that does not have an improved seal unit installed in accordance with the ACCOMPLISHMENT INSTRUCTIONS section of Pilatus Service Bulletin No. 32-018, dated March 6, 1998.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Small Airplane Directorate, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

(e) Questions or technical information related to Pilatus Service Bulletin No. 32-018, dated March 6, 1998, should be directed to Pilatus Aircraft Ltd., Customer Liaison Manager, CH-6371 Stans, Switzerland; telephone: +41 41 619 6233; facsimile: +41 41 610 3351. This service information may be examined at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

(f) The replacements required by this AD shall be done in accordance with Pilatus Service Bulletin No. 32-018, dated March 6, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Pilatus Aircraft Ltd., Customer Liaison Manager, CH-6371 Stans, Switzerland. Copies may be inspected at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in Swiss AD HB 98-069, dated March 23, 1998.

(g) This amendment becomes effective on September 21, 1998.

Issued in Kansas City, Missouri, on July 28, 1998.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-20838 Filed 8-6-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-CE-112-AD; Amendment 39-10690; AD 98-16-14]

RIN 2120-AA64

Airworthiness Directives; Pilatus Britten-Norman Ltd. BN-2, BN-2A, BN-2B, and BN-2T Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to all Pilatus Britten-Norman Ltd. (Pilatus Britten-Norman) BN-2, BN-2A, BN-2B, and BN-2T series airplanes. This AD requires replacing the attachment bolts, nuts and washers of the lower fitting of the main landing gear (MLG), and adjusting the torque values of the nuts. This AD is the result of mandatory continuing airworthiness

information (MCAI) issued by the airworthiness authority for the United Kingdom. The actions specified by this AD are intended to prevent the bolts that attach the lower fitting of the MLG to the nacelle from becoming threadbound, which could result in structural failure of the MLG with consequent loss of control of the airplane during takeoff, taxi, or landing operations.

DATES: Effective September 21, 1998.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of September 21, 1998.

ADDRESSES: Service information that applies to this AD may be obtained from Pilatus Britten-Norman Limited, Bembridge, Isle of Wight, United Kingdom PO35 5PR; telephone: 44-1983 872511; facsimile: 44-1983 873246. This information may also be examined at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 97-CE-112-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Mr. Roger Chudy, Aerospace Engineer, Small Airplane Directorate, Aircraft Certification Service, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone: (816) 426-6934; facsimile: (816) 426-2169.

SUPPLEMENTARY INFORMATION:

Events Leading to the Issuance of This AD

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to all Pilatus Britten-Norman BN-2, BN-2A, BN-2B, and BN-2T series airplanes was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on March 19, 1998 (63 FR 13379). The NPRM proposed to require replacing the washers on the attachment bolts of the lower fitting of the MLG. Accomplishment of the proposed action as specified in the NPRM would be in accordance with Pilatus Britten-Norman Service Bulletin BN2/SB.231, Initial Issue, dated October 17, 1996.

The NPRM was the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for the United Kingdom.

After issuance of the NPRM, Pilatus Britten-Norman informed the FAA that Service Bulletin BN2/SB.231 has been

revised to the Issue 2 status (dated October 1, 1997). This revision changes the procedures to specify replacing the attachment bolts and nuts of the lower fitting of the MLG instead of re-using the existing bolts and nuts. This service information also specifies procedures to adjust the torque loading values of the bolts.

In addition, the FAA has realized that the Model BN-2T-4R airplanes were inadvertently omitted from the proposed AD. At that time, the FAA determined that the Model BN-2T-4R airplanes are of similar type design to those currently listed in the NPRM.

This prompted the FAA to issue a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to all Pilatus Britten-Norman BN-2, BN-2A, BN-2B, BN-2T, and BN-2T-4R series airplanes. This proposal was published in the **Federal Register** as a supplemental NPRM on May 28, 1998 (63 FR 29159). The supplemental NPRM proposed to also require replacing the attachment bolts and nuts of the lower fitting of the MLG and adjusting the torque values of the nuts. Accomplishment of the proposed action as specified in the supplemental NPRM would be in accordance with the service information previously referenced.

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the one comment received.

Comment Disposition

Pilatus Britten-Norman states that the proposed AD should not apply to the Model BN-2T-4R airplanes. These airplanes utilize a different type wing and an uprated landing gear construction from the rest of the affected models.

After re-examining all information related to this subject, the FAA concurs and has removed the Model BN-2T-4R airplanes from the final rule.

The FAA's Determination

After careful review of all available information related to the subject presented above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed except for minor editorial corrections. The FAA has determined that these minor corrections will not change the meaning of the AD and will not add any additional burden upon the public than was already proposed.