

## BILLING CODE 4910-59-C

5. The mounting height of the DRLs on the non complying vehicles complies with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 108.

6. GM has not identified any accidents, injuries or warranty reports that are associated with this condition on the non complying vehicles.

For all of the above reasons, GM argues that this noncompliance is inconsequential to motor vehicle safety. In consideration of the foregoing, GM has applied for a decision that it be exempted from the notification and remedy provisions of 49 USC 30118 and 30120 for this specific noncompliance with FMVSS No.108.

Interested persons are invited to submit written data, views, and arguments on the application described above. Comments should refer to the docket number and be submitted to: Docket Management, Room PL-401, 400 Seventh Street, SW, Washington, DC 20590. It is requested but not required that six copies be submitted. Docket hours are 10:00 A.M. to 5:00 P.M.

All comments received before the close of business on the closing date indicated below will be considered. The application and supporting materials, and all comments received after the closing date, will also be filed and will be considered to the extent practicable. When the application is granted or denied, the notice will be published in the **Federal Register** pursuant to the authority indicated below.

Comment closing date: June 17, 1999.

(49 U.S.C. 30118 and 30120; delegations of authority at 49 CFR 1.50 and 501.8)

Issued on: May 12, 1999.

**L. Robert Shelton,**

*Associate Administrator for Safety Performance Standards.*

[FR Doc. 99-12467 Filed 5-17-99; 8:45 am]

BILLING CODE 4910-59-P

## DEPARTMENT OF TRANSPORTATION

### National Highway Traffic Safety Administration

[Docket No. NHTSA-99-5056; Notice 1]

#### Application for Determination of Inconsequential Noncompliance to Federal Motor Vehicle Safety Standard 108—Lamps, Reflective Devices and Associated Equipment

General Motors Corporation (GM), has determined 1997 GM S10 Electric Trucks (S10 trucks equipped with an electric propulsion system) fail to meet the turn signal bulb outage requirements

found in S5.5.6 of Federal Motor Vehicle Safety Standard (FMVSS) 108—*Lamps, Reflective Devices and Associated Equipment*. Pursuant to Title 49 of the United States Code, Sections 30118 and 30120, GM has petitioned the National Highway Traffic Safety Administration (NHTSA) for a decision that the noncompliance is inconsequential as it relates to motor vehicle safety. In accordance with 49 CFR 556.4(b)(6), GM has also submitted a 49 CFR 573.5 noncompliance notification to the agency.

This notice of receipt of an application is published under 49 U.S.C. 30118 and 30120 and does not represent an agency decision or other exercise of judgement concerning the merits of the application.

FMVSS 108 S5.5.6 requires:

S5.5.6 Each vehicle equipped with a turn signal operating unit shall also have an illuminated pilot indicator. Failure of one or more turn signal lamps to operate shall be indicated in accordance with SAE Standard J588e, Turn Signal Lamps, September 1970, except when a variable-load turn signal flasher is used on a truck, bus, or multipurpose passenger vehicle 80 or more inches in overall width, on a truck that is capable of accommodating a slide-in camper, or on any vehicle equipped to tow trailers.

The design of the S10 Electric Truck is based on the design of conventional S10 trucks powered by internal combustion engines, with modifications to accommodate the electric propulsion system. The conventional S10 trucks are capable of towing, have a variable load flasher, and, therefore, are not required by the Standard to provide bulb outage indication. The use of an S10 Electric Truck for towing is not practical and is not recommended. The impact of that fact was overlooked in the process of carrying over the design of the turn signal system from the conventional S10 to the S10 Electric and, therefore, the non complying vehicles were not equipped to indicate bulb outage and do not meet that requirement of FMVSS 108 S5.5.6. This was corrected in the 1998 model year production of the S10 Electric.

GM believes that this noncompliance is inconsequential to motor vehicle safety for these reasons:

The S10 Electric Trucks are identical in appearance to the normal production vehicles. Except for the lack of towing capability, the subject vehicles are functionally the same as fully compliant S10 trucks.

There were only 209 vehicles produced and, therefore, the exposure is extremely small.

Most of the subject vehicles are part of commercial and government fleets (they have

been purchased by electric utility companies and state and municipal government agencies). As such, they will be exposed to routine maintenance schedules that are more rigorous than the average consumer practices.

Most trucks currently produced are capable of trailer towing and, thus, are not required to detect bulb outage. As a result, individuals and fleets who are accustomed to truck operation do not necessarily have an expectation that turn signal bulb outage will be indicated. In addition, other lamps required by FMVSS 108 are not required to provide bulb outage indication. As a result, the lack of that feature on these vehicles is not likely to be noticed by the vehicle operators, and they will continue to discover turn signal bulb outage the way they would on other trucks that are capable of towing.

GM is not aware of field complaints due to the subject condition.

GM asserts that the noncomplying trucks present the same level of safety as the millions of other vehicles with variable load flashers currently on the roads and highways. GM thus argues that this noncompliance is inconsequential as it relates to motor vehicle safety. In consideration of the foregoing, GM petitions that it be exempted from the notification and remedy provisions of the Safety Act for this specific noncompliance with FMVSS No. 108.

Interested persons are invited to submit written data, views, and arguments on the application described above. Comments should refer to the docket number and be submitted to: Docket Management, Room PL-401, 400 Seventh Street, SW, Washington, DC 20590. It is requested but not required that six copies be submitted. Docket hours are 10:00 A.M. to 5:00 P.M.

All comments received before the close of business on the closing date indicated below will be considered. The application and supporting materials, and all comments received after the closing date, will also be filed and will be considered to the extent possible. When the application is granted or denied, the notice will be published in the **Federal Register** pursuant to the authority indicated below.

Comment closing date: June 17, 1999.

(49 U.S.C. 30118 and 30120; delegations of authority at 49 CFR 1.50 and 501.8)

Issued on: May 12, 1999.

**L. Robert Shelton,**

*Associate Administrator for Safety Performance Standards.*

[FR Doc. 99-12466 Filed 5-17-99; 8:45 am]

BILLING CODE 4910-59-P