

(b) The enzyme-linked immunosorbent assay (ELISA) may be used as a screening test for avian influenza. Use only federally licensed ELISA kits and follow the manufacturer's instructions. All ELISA-positive serum samples must be confirmed with the AGID test conducted in accordance with paragraph (a) of this section.

§ 147.11 [Amended]

28. Section 147.11 would be amended as follows:

a. In paragraph (b)(2)(iii) the words "A group D colony lift assay may be utilized to signal the presence of the hard-to-detect group D salmonella colonies on agar culture plates." would be added after the final sentence.

b. In paragraph (b)(2)(v), the words "at the National Veterinary Services Laboratory" would be removed.

29. A new § 147.18 would be added to read as follows:

§ 147.18 Chick meconium testing procedure for salmonella.

Procedure:

(a) Record the date, source, and flock destination on the "Meconium Worksheet."

(b) Shake each plastic bag of meconium until a uniform consistency is achieved.

(c) Transfer a 25 gm sample of meconium to a sterile container. Add 225 mL of a preenrichment broth to each sample (this is a 1:10 dilution), mix gently, and incubate at 37 °C for 18-24 hours.

(d) Enrich the sample with selective enrichment broth for 24 hours at 42 °C.

(e) Streak the enriched sample onto brilliant green-Novobiocin (BGN) agar and xylose-lysine-tergitol 4 (XLT4) agar.

(f) Incubate both plates at 35 °C for 24 hours and process suspect salmonella colonies according to § 147.11.

30. In § 147.43, paragraphs (d)(1) through (d)(4) would be redesignated as paragraphs (d)(3) through (d)(6), respectively, and new paragraphs (d)(1), (d)(2), (d)(7), and (d)(8) would be added to read as follows:

§ 147.43 General Conference Committee.

* * * * *

(d) * * *

(1) Advise and make recommendations to the Department on the relative importance of maintaining, at all times, adequate departmental funding for the NPIP to enable the Senior Coordinator and staff to fully administer the provisions of the Plan.

(2) Advise and make yearly recommendations to the Department with respect to the NPIP budget well in

advance of the start of the budgetary process.

* * * * *

(7) Serve as a direct liaison between the National Poultry Improvement Plan and the United States Animal Health Association.

(8) Advise and make recommendations to the Department regarding NPIP involvement or representation at poultry industry functions and activities as deemed necessary or advisable for the purposes of the NPIP.

§ 147.45 [Amended]

31. Section 147.45 would be amended by removing the words "and E" and adding the words "E, and F" in their place.

32. In § 145.46, the introductory text of paragraph (a) would be amended by removing the word "four" and adding the word "five" in its place, and a new paragraph (a)(5) would be added to read as follows:

§ 147.46 Committee consideration of proposed changes.

(a) * * *

(5) Ostriches, emus, rheas, and cossowaries.

* * * * *

Done in Washington, DC, this 4th day of August 1999.

Bobby R. Acord,

Acting Administrator, Animal and Plant Health Inspection Service.

[FR Doc. 99-20540 Filed 8-9-99; 8:45 am]

BILLING CODE 3410-34-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-280-AD]

Airworthiness Directives; Raytheon (Beech) Model 400A Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Raytheon (Beech) Model 400A airplanes. This proposal would require replacement of the fuel drain tube assembly in the aft fuselage with a new, modified assembly. This proposal is prompted by a report of chafing of the fuel tube assembly against the elevator control cable due to inadequate clearance between the components. The

actions specified by the proposed AD are intended to prevent chafing of the fuel drain tube assembly, which could result in fuel leakage from the fuel drain tube assembly and consequent risk of a fire.

DATES: Comments must be received by September 9, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-280-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Raytheon Aircraft Company, Manager Service Engineering, Hawker Customer Support Department, P. O. Box 85, Wichita, Kansas 67201-0085. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington or at the FAA, Small Airplane Directorate, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas.

FOR FURTHER INFORMATION CONTACT: Scott West, Aerospace Engineer, Systems and Propulsion Branch, ACE-116W, FAA, Small Airplane Directorate, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4146; fax (316) 946-4407.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact

concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 98-NM-280-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-280-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received a report of chafing on the fuel drain tube assembly in the aft fuselage on a Raytheon (Beech) Model 400A airplane. Further investigation revealed that the elevator control cable contacted the fuel drain tube assembly due to inadequate clearance between the components. This condition, if not corrected, could result in fuel leakage from the fuel drain tube assembly and consequent risk of a fire.

Explanation of Relevant Service Information

The FAA has reviewed and approved Raytheon Aircraft Service Bulletin SB.28-3076, dated October, 1997, which describes procedures for replacement of the existing fuel drain tube assembly with a new, modified assembly. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously.

Cost Impact

There are approximately 92 airplanes of the affected design in the worldwide fleet. The FAA estimates that 72 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 8 work hours per airplane to accomplish the proposed action, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$21 per airplane. Based on these figures, the cost

impact of the proposed AD on U.S. operators is estimated to be \$36,072, or \$501 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. However, the FAA has been advised that manufacturer warranties are available for parts associated with accomplishing the replacement action required by this proposed AD. Therefore, the future economic cost impact of this rule on U.S. operators may be less than the cost impact figure indicated above.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Raytheon Aircraft Company (Formerly Beech): Docket 98-NM-280-AD.

Applicability: Model 400A airplanes, serial numbers RK-1 through RK-92 inclusive, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent chafing of the fuel drain tube assembly, which could result in fuel leakage from the fuel drain tube assembly and consequent risk of fire, accomplish the following:

Replacement

(a) At the next scheduled inspection, but no later than 200 flight hours after the effective date of this AD, replace the existing aft fuselage fuel drain tube assembly, part number (P/N) 128-920151-1, with a new, modified tube assembly, P/N 128-920237-1, in accordance with Raytheon Aircraft Service Bulletin SB.28-3076, dated October, 1997.

Spares

(b) As of the effective date of this AD, no person shall install a fuel drain tube assembly, P/N 128-920151-1, on any airplane.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Wichita Aircraft Certification Office (ACO), FAA, Small Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Wichita ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on August 4, 1999.

D.L. Riggin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 99-20502 Filed 8-9-99; 8:45 am]
BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-71-AD]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas MD-11 and MD-11F Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain McDonnell Douglas MD-11 and MD-11F series airplanes. This proposal would require a one-time inspection to determine if metallic transitions are installed on wire harnesses of the tail tank fuel transfer pumps, and to determine if damaged wires are present; and repair, if necessary. This proposal also would require repetitive inspections of the repaired area; and a permanent modification of the wire harnesses if metallic transitions are not installed, which would terminate the repetitive inspections. This proposal is prompted by a report of chafing and damage to a wire harness of a tail tank fuel transfer pump. The actions specified by the proposed AD are intended to prevent wire chafing and damage, which could result in an inoperative fuel transfer pump and/or an increased risk of a fire or explosion from a fuel leak.

DATES: Comments must be received by September 24, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-71-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Aircraft Group,

Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Dept. C1-L51 (2-60). This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California.

FOR FURTHER INFORMATION CONTACT:

Roscoe Van Dyke, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5254; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NM-71-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-71-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received a report of chafing and damage to a wire harness of a tail tank fuel transfer pump on a McDonnell Douglas Model MD-11 series airplane. The cause of such chafing and damage has been attributed to wires chafing against a combination of wire mesh tape and braided shielding, which were installed during production as a substitute for metallic transitions at the wiring harness breakouts. Chafing or damage of a wire harness, if not corrected, could result in an inoperative fuel transfer pump and/or an increased risk of a fire or explosion from a fuel leak.

Explanation of Relevant Service Information

The FAA has reviewed and approved McDonnell Douglas Alert Service Bulletin MD11-28A101, dated August 24, 1998, which describes procedures for a one-time visual inspection to determine if metallic transitions are installed on the wire harnesses of the tail tank fuel transfer pumps, and to determine if damaged wires are present; repair, if necessary; and repetitive inspections of the repaired area. The FAA also has reviewed and approved McDonnell Douglas Service Bulletin MD11-28-102, Revision 01, dated June 23, 1999, which describes procedures for a permanent modification of the wire harnesses if metallic transitions are not installed. Accomplishment of the permanent modification would eliminate the need for the repetitive inspections in service bulletin MD11-28A101. Accomplishment of the actions specified in the service bulletins is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the service bulletins described previously, except as discussed below.

Differences Between the Proposed Rule and the Relevant Service Information

Operators should note that, although McDonnell Douglas Alert Service Bulletin MD11-28A101, dated August 24, 1998, recommends accomplishing the visual inspection within 15 days (after the release of the service bulletin), the FAA has determined that a compliance time of 30 days would be appropriate. In developing an appropriate compliance time for the