

whether such walnuts are inshell or shelled, the quantity of such walnuts received, the country of origin for such walnuts, the name of the DFA of California inspector who issued the product tag, and the date such tag was issued.

Dated: August 17, 1999.

Robert C. Keeney,

Deputy Administrator, Fruit and Vegetable Programs.

[FR Doc. 99-21666 Filed 8-18-99; 8:45 am]

BILLING CODE 3410-02-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 96-NM-206-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 767 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Proposed rule; withdrawal.

SUMMARY: This action withdraws a notice of proposed rulemaking (NPRM) that proposed a new airworthiness directive (AD), applicable to certain Boeing Model 767 series airplanes. That action would have required replacement of the existing retaining bolt of the attendant seat lap belt with a new bolt and a washer. Since the issuance of the NPRM, the Federal Aviation Administration (FAA) has received new data indicating that the proposed action has already been accomplished on all affected airplanes. Accordingly, the proposed rule is withdrawn.

FOR FURTHER INFORMATION CONTACT:

Meghan Gordon, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2207; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION:

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to add a new airworthiness directive (AD), applicable to certain Boeing Model 767 series airplanes, was published in the **Federal Register** as a Notice of Proposed Rulemaking (NPRM) on June 6, 1997 (62 FR 31020). The proposed rule would have required replacement of the existing retaining bolt of the attendant seat lap belt with a new bolt and a washer. That action was prompted by reports indicating that, due to a missing

washer, the bolt end fittings of the double flight attendant seats can become loose. The proposed actions were intended to ensure that a washer between the bolt head and bushing is installed. A missing washer could allow movement of the bolt end fittings, which can cause the restraint belts to release and, consequently, result in injury to the flight attendants.

Actions Since Issuance of the NPRM

Since the issuance of that NPRM, the FAA has received a comment from the airplane manufacturer indicating that the replacement of the existing retaining bolt of the attendant seat lap belt with a new bolt and a washer, in accordance with Boeing Service Bulletin 767-25-0217, dated January 13, 1994, has been accomplished on all affected airplanes. Though the manufacturer did not provide documentation to support its statement, the FAA also has received substantiating documentation from each affected operator that the service bulletin has been incorporated on its fleet of airplanes. In the case of one operator, the FAA contacted the Principal Maintenance Inspector (PMI) to determine whether the replacement had been accomplished on that operator's affected airplanes. The PMI verified that the service bulletin had been accomplished on all affected airplanes in that operator's fleet.

In addition, the airplane manufacturer has also updated the Illustrated Parts Catalog to include the washer that corrects the unsafe condition in the seat assembly; therefore, the unsafe condition is not likely to be reintroduced in the future.

FAA's Conclusions

Based upon the FAA's review of the data submitted by the affected operators and the airplane manufacturer, the FAA has determined that the previously identified unsafe condition no longer exists. Accordingly, the proposed rule is hereby withdrawn.

Withdrawal of this notice of proposed rulemaking constitutes only such action, and does not preclude the agency from issuing another notice in the future, nor does it commit the agency to any course of action in the future.

Regulatory Impact

Since this action only withdraws a notice of proposed rulemaking, it is neither a proposed nor a final rule and therefore, is not covered under Executive Order 12866, the Regulatory Flexibility Act, or DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979).

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Withdrawal

Accordingly, the notice of proposed rulemaking, Docket 96-NM-206-AD, published in the **Federal Register** on June 6, 1997 (62 FR 31020), is withdrawn.

Issued in Renton, Washington, on August 13, 1999.

D. L. Riggan,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 99-21574 Filed 8-18-99; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-351-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-300, -400, and -500 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all Boeing Model 737-300, -400 and -500 series airplanes. This proposal would require replacement, with new parts, of the existing actuators or the rod ends on the existing actuators at wing leading edge slat positions 1, 2, 5, and 6. This proposal is prompted by reports indicating that the rod ends on several leading edge slat actuators have fractured. The actions specified by the proposed AD are intended to prevent fatigue cracking of the rod ends of the leading edge slat actuators, which could result in uncommanded deployment of the wing leading edge slat and consequent reduced controllability of the airplane.

DATES: Comments must be received by October 4, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-351-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00

p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Robert C. Jones, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, Washington 98055-4056; telephone (425) 227-1118; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 98-NM-351-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-351-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received reports of fractured rod ends on several actuators for the wing leading edge slats on

Boeing Model 737-300, -400, and -500 series airplanes. One reported case of an actuator rod end fracture resulted in an air turnback after the airplane experienced uncommanded roll during flight. It has been determined that these fractures are the result of fatigue cracking. Failure of the actuator rod end, under certain flight conditions, could result in an uncommanded deployment of the affected wing leading edge slat and consequent reduced controllability of the airplane.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Alert Service Bulletin 737-27A1211, dated November 19, 1998, which describes procedures for replacement of the existing wing leading edge slat actuator with a new actuator, or replacement of the rod end on the existing leading edge slat actuator. Accomplishment of either of these actions specified in the alert service bulletin is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the alert service bulletin described previously.

Cost Impact

There are approximately 1,897 airplanes of the affected design in the worldwide fleet. The FAA estimates that 720 airplanes of U.S. registry would be affected by this proposed AD.

Replacement of the leading edge slat actuator with an actuator that has a new rod end is proposed as one option for compliance with this AD action. Replacement of the actuators on slat positions 1, 2, 5, and 6 would take approximately 3 hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Required parts cost approximately \$32,252 per airplane. Based on these figures, the cost impact of the installation of actuators with new rod ends as proposed as an option by this AD on U.S. operators is estimated to be \$32,432 per airplane.

In lieu of installation of an actuator with a new rod end, this proposed AD provides an option for replacement of the rod ends on the existing actuators. This action would take approximately 4 work hours per airplane, at an average labor rate of \$60 per work hour. Required parts would cost between approximately \$5,928 and \$21,544 per

airplane. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be between \$6,168 and \$21,784 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing: Docket 98-NM-351-AD.

Applicability: Model 737-300, -400, and -500 series airplanes; line numbers 1001 through 3063 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously. To prevent fatigue cracking of the rod ends on the leading edge slat actuators, which could result in uncommanded deployment of the wing leading edge slat and consequent reduced controllability of the airplane, accomplish the following:

(a) Within 24 months after the effective date of this AD: Replace the leading edge slat actuator with an actuator that has a new rod end, or replace the rod end on the existing slat actuator with a new rod end, at slat positions 1, 2, 5, and 6; in accordance with the Accomplishment Instructions in Boeing Alert Service Bulletin 737-27A1211, dated November 19, 1998.

Spares

(b) As of the effective date of this AD, no person shall install any part having a part number identified in the "Existing Part Number" column of Section 2.E. of Boeing Alert Service Bulletin 737-27A1211, dated November 19, 1998, on any airplane.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on August 13, 1999.

D. L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 99-21575 Filed 8-18-99; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF THE INTERIOR

Minerals Management Service

30 CFR Part 206

RIN 1010-AC59

Valuation of Federal Geothermal Resources

AGENCY: Minerals Management Service, Interior.

ACTION: Advance notice of proposed rulemaking.

SUMMARY: In response to deregulation of the electric power market in California and resulting changes to the geothermal industry, the Minerals Management Service (MMS) is considering amending its regulations regarding the valuation, for royalty purposes, of Federal geothermal resources used to generate electricity. MMS specifically seeks comments on the use of the netback procedure to value geothermal resources that are not sold under arm's-length contracts, whether the existing netback procedure should be modified, and whether there are reasonable alternatives to netback valuation. MMS also seeks comments on any other aspects of the rules including the rules governing valuation of resources used in direct utilization processes, particularly alternatives for valuing those resources that are not subject to a sales transaction.

DATES: Comments must be received on or before October 18, 1999.

ADDRESSES: The mailing address for written comments regarding geothermal valuation issues is David S. Guzy, Chief, Rules and Publications Staff, Minerals Management Service, Royalty Management Program, P.O. Box 25165, MS 3021, Denver, Colorado 80225. Courier address is Building 85, Room A-613, Denver Federal Center, Denver, Colorado 80225. E-mail address is RMP.comments@mms.gov. For additional details, see **SUPPLEMENTARY INFORMATION**.

FOR FURTHER INFORMATION CONTACT: David S. Guzy, Chief, Rules and Publications Staff, MMS, Royalty Management Program, at telephone (303) 231-3432, FAX (303) 231-3385, or e-mail david.guzy@mms.gov.

SUPPLEMENTARY INFORMATION:

Public Comment Procedure: If you wish to comment, you may submit your comments by any one of several methods. You may mail comments to David S. Guzy, Chief, Rules and Publications Staff, Minerals Management Service, Royalty Management Program, P.O. Box 25165, MS 3021, Denver, CO 80225-0165. Courier or overnight delivery address is Building 85, Room A-613, Denver Federal Center, Denver, Colorado 80225. You may also comment via the Internet to RMP.comments@mms.gov. Please submit Internet comments as an ASCII file avoiding the use of special characters and any form of encryption. Please also include "Attn.: RIN 1010-AC59" and your name and return address in your Internet message. If you do not receive a confirmation from the system that we have received your Internet message, contact David S. Guzy directly at (303) 231-3432.

We will post public comments after the comment period closes on the Internet at <http://www.rmp.mms.gov>. You may arrange to view paper copies of the comments by contacting David S. Guzy, Chief, Rules and Publications Staff, telephone (303)231-3432, FAX (303)231-3385. Our practice is to make comments, including names and addresses of respondents, available for public review on the Internet and during regular business hours at our offices in Lakewood, Colorado. Individual respondents may request that we withhold their home address from the rulemaking record, which we will honor to the extent allowable by law. There also may be circumstances in which we would withhold from the rulemaking record a respondent's identity, as allowable by law. If you wish us to withhold your name and/or address, you must state this prominently at the beginning of your comment. However, we will not consider anonymous comments. We will make all submissions from organizations or businesses, and from individuals identifying themselves as representatives or officials of organizations or businesses, available for public inspection in their entirety.

I. Background

The Geothermal Steam Act of 1970, as amended (30 U.S.C. 1001-1025), requires the lessee to pay royalty to the United States on the amount or value of steam, or any other form of heat or energy derived from production under the lease and sold or used by the lessee or reasonably susceptible to sale or use by the lessee. Federal geothermal leases