

§ 3019.1 Purpose.

* * * *

(b) This part also applies specifically to the grants, agreements and subawards to institutions of higher education, hospitals, and other non-profit organizations that are awarded to carry out the following entitlement programs:

(1) Entitlement grants under the following programs authorized by The Richard B. Russell National School Lunch Act:

(i) National School Lunch Program, General Assistance (section 4 of the Act),

(ii) Commodity Assistance (section 6 of the Act),

(iii) National School Lunch Program, Special Meal Assistance (section 11 of the Act),

(iv) Summer Food Service Program for Children (section 13 of the Act), and

(v) Child and Adult Care Food Program (section 17 of the Act).

(2) Entitlement grants under the following programs authorized by The Child Nutrition Act of 1966:

(i) Special Milk Program for Children (section 3 of the Act), and

(ii) School Breakfast Program (section 4 of the Act).

(3) Entitlement grants for State Administrative Expenses under The Food Stamp Act of 1977 (section 16 of the Act).

9. In § 3019.2, remove the last sentence in paragraph (e) introductory text and paragraphs (e)(1) through (e)(5). [FR Doc. 00-20489 Filed 8-11-00; 8:45 am]

BILLING CODE 3410-90-P

SMALL BUSINESS ADMINISTRATION**13 CFR Part 120****Business Loan Programs**

AGENCY: Small Business Administration.

ACTION: Final rule; correcting amendment.

SUMMARY: The U.S. Small Business Administration (SBA) published a final rule governing 7(a) loan securitizations on February 10, 1999. In that rule, SBA inadvertently omitted a sentence in the section covering capital requirements for securitizing institutions ("securitizers"). This document adds that sentence.

DATES: Effective on August 14, 2000.

FOR FURTHER INFORMATION CONTACT: James W. Hammersley, Director, Secondary Market Sales, (202) 205-7505.

SUPPLEMENTARY INFORMATION: SBA published a final rule in the **Federal**

Register on February 10, 1999, (64 FR 6503), governing 7(a) loan securitizations. This correction adds a sentence to § 120.425(a), on capital requirements, that was inadvertently omitted. Section 120.425(a) provides that all "securitizers must be considered to be 'well capitalized' by their regulator." It further states that "SBA, as the regulator, will consider a nondepository institution to be 'well capitalized' if it maintains a minimum unencumbered paid in capital and paid in surplus equal to at least 10 percent of its assets, excluding the guaranteed portion of 7(a) loans." This correction adds that "[t]he capital charge applies to the remaining balance outstanding on the unguaranteed portion of the securitizer's 7(a) loans in its portfolio and in any securitization pools."

This correction is consistent with notice provided in the preamble to the final rule published on February 10, 1999 (64 FR 6503). That preamble stated that commenters requested SBA to clarify that "the capital charge applies not only to the unguaranteed portion of the securitizer's 7(a) loans in the portfolio but also to the remaining balance outstanding in the securitization pools" and that SBA "incorporated" this clarification "into the final rule."

By making this correction, SBA is incorporating the clarification, as intended, into the final rule.

List of Subjects in 13 CFR Part 120

Loan programs—business, Small businesses.

Accordingly, SBA amends 13 CFR part 120 by making the following correcting amendment:

PART 120—[CORRECTED]

1. The authority citation for part 120 continues to read as follows:

Authority: 15 U.S.C. 634(b)(6) and 636(a) and (h).

2. In § 120.425, amend paragraph (a) by adding a new sentence after the fourth sentence to read as follows:

§ 120.425 What are the minimum elements that SBA will require before consenting to a securitization?

* * * *

(a) * * * The capital charge applies to the remaining balance outstanding on the unguaranteed portion of the

securitizer's 7(a) loans in its portfolio and in any securitization pools. * * *

Aida Alvarez,
Administrator.

[FR Doc. 00-19339 Filed 8-11-00; 8:45 am]

BILLING CODE 8025-01-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 99-NM-331-AD; Amendment 39-11769; AD 2000-11-21]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A319, A320, and A321 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; correction.

SUMMARY: This document corrects information in an existing airworthiness directive (AD) that applies to certain Airbus Model A319, A320, and A321 series airplanes. That AD currently requires a one-time general visual inspection to determine the part number and serial number of the spoiler servocontrol, and corrective action, if necessary. This document corrects the type of inspection required by this AD, and corrects references to certain paragraphs of the applicable service bulletins. These corrections are necessary to ensure that operators are notified of the type of inspection required and the correct paragraph references of the applicable service bulletins.

DATES: Effective July 18, 2000.

The incorporation by reference of certain publications listed in the regulations was approved previously by the Director of the Federal Register as of July 18, 2000 (65 FR 37017, June 13, 2000).

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: On June 1, 2000, the Federal Aviation Administration (FAA) issued AD 2000-11-21, amendment 39-11769, which applies to certain Airbus Model A319, A320, and A321 series airplanes. That AD requires a one-time general visual inspection to determine the part number

and serial number of the spoiler servocontrol, and corrective action, if necessary. That AD was prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions required by that AD are intended to prevent failure of the spoiler servocontrol piston rod, which could result in reduced controllability of the airplane.

Need for the Correction

Paragraph (a) of AD 2000-11-21 specifies a "general visual inspection." However, the FAA points out that since the inspection is to determine the part number and serial number of certain components, it is unnecessary to require a general visual inspection. Likewise, it is unnecessary to include the definition of that inspection in Note 2 following paragraph (a) of that AD. Instead, the FAA considers that an "inspection" rather than a "general visual inspection" adequately describes the action required by this AD to determine the part number and serial number for the spoiler servocontrols. Paragraph (a) of this AD reflects these changes.

In addition, the FAA recently obtained information that paragraphs (a) and (b) of AD 2000-11-21 contain incorrect paragraph references to the applicable service bulletins. The information specifies that paragraph (a) should reference paragraph 3.B.(1)(b) instead of paragraph 2.B.(1)(b) of the applicable service bulletins, and that paragraph (b) should reference paragraph 3.B.(1)(b)1 instead of paragraph 2.B.(1)(b)1. However, the FAA points out that paragraphs 2.B.(1)(b) and 2.B.(1)(b)1 are the correct paragraph references specified by Airbus Service Bulletin A320-17-1126 and A320-27-1127, both dated April 26, 1999. In addition, paragraphs 3.B.(1)(b) and 3.B.(1)(b)1 are the correct paragraph references specified by Revision 01 of those service bulletins, both dated October 6, 1999. Therefore, in paragraph (a) of this AD, the FAA has added a reference to paragraph 3.B.(1)(b) of Revision 01 of the service bulletins, and in paragraph (b) of this AD, the FAA has added a reference to paragraph 3.B.(1)(b)1 of Revision 01 of the service bulletins.

The FAA has determined that such corrections to paragraphs (a) and (b) of AD 2000-11-21 are necessary. These corrections will ensure that operators are notified of the correct type of inspection required by this AD, and the correct paragraph references of the applicable service bulletins.

Correction of Publication

This document corrects the type of inspection required by this AD, corrects certain paragraph references to the applicable service bulletins, and adds the AD as an amendment to section 39.13 of the Federal Aviation Regulations (14 CFR 39.13).

The AD is reprinted in its entirety for the convenience of affected operators. The effective date of the AD remains July 18, 2000.

Since this action only corrects the type of inspection required (and removes Note 2 defining the previously specified inspection), and corrects certain paragraph references to the applicable service bulletins, it has no adverse economic impact and imposes no additional burden on any person. Therefore, the FAA has determined that notice and public procedures are unnecessary.

List of Subject in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Correction

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Corrected]

2. Section 39.13 is amended by correctly adding the following airworthiness directive (AD):

2000 21 Airbus Industrie: Amendment 39-11769. Docket 99-NM-331-AD.

Applicability: The following models, certificated in any category, excluding those on which Airbus Service Bulletin A320-27-1126, dated April 26, 1999 (for Model A319 and 321 series airplanes); or A320-27-1127, dated April 26, 1999, or Revision 01, dated October 6, 1999 (for Model A320 series airplanes); has been accomplished:

- Model A319 series airplanes, serial numbers (S/N) 0546 through 0972 inclusive;
- Model A320 series airplanes, S/N 0002 through 0842 inclusive, 0846 through 0859 inclusive, 0865, 0866, and 0872 through 0960 inclusive; and
- Model A321 series airplanes, S/N 0364 through 0974 inclusive.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in

the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the servocontrol piston rod, which could result in reduced controllability of the airplane, accomplish the following:

Inspection

(a) At the applicable time specified by paragraph (a)(1) or (a)(2) of this AD: Perform an inspection to determine the part number and serial number for the spoiler servocontrols, in accordance with Airbus Service Bulletin A320-27-1126, dated April 26, 1999, or Revision 01, dated October 6, 1999 (for Model A319 and A321 series airplanes); or Airbus Service Bulletin A320-27-1127, dated April 26, 1999, or Revision 01, dated October 6, 1999 (for Model A320 series airplanes); as applicable. If the part number and serial number are identified in paragraph 2.B.(1)(b) of the Accomplishment Instructions of the original service bulletins, or in paragraph 3.B.(1)(b) of the Accomplishment Instructions of Revision 01 of the service bulletins; as applicable; prior to further flight, perform applicable corrective actions (including removal, reidentification of the servocontrol, and replacement of the servocontrol with a modified part) as specified in the applicable service bulletin.

(1) For Model A319 and A321 series airplanes: Inspect within 2 months after the effective date of this AD.

(2) For Model A320 series airplanes: Inspect within 28 months after the effective date of this AD.

Spares

(b) As of the effective date of this AD, no person shall install on any airplane a spoiler servocontrol having part number 31077-050, 31077-060, or 31077-110; and S/N 0001 to 3499, except those serial numbers excluded in paragraph 2.B.(1)(b)1 of the Accomplishment Instructions of Airbus Service Bulletin A320-27-1126, dated April 26, 1999; or in paragraph 3.B.(1)(b)1 of the Accomplishment Instructions of Airbus Service Bulletin A320-27-1126, Revision 01, dated October 6, 1999; unless that servocontrol has been inspected, and corrective actions have been performed, in accordance with the requirements of this AD.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators

shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The actions shall be done in accordance with Airbus Service Bulletin A320-27-1126, including Appendices 01 and 02, dated April 26, 1999; Airbus Service Bulletin A320-27-1126, Revision 01, including Appendices 01 and 02, dated October 6, 1999; Airbus Service Bulletin A320-27-1127, including Appendices 01 and 02, dated April 26, 1999; or Airbus Service Bulletin A320-27-1127, Revision 01, including Appendices 01 and 02, dated October 6, 1999, as applicable. The incorporation by reference of these documents was approved previously by the Director of the Federal Register as of July 18, 2000 (65 FR 37017, June 13, 2000). Copies may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in French airworthiness directive 1999-362-139(B), dated September 8, 1999.

Effective Date

(f) The effective date of this amendment remains July 18, 2000.

Issued in Renton, Washington, on August 8, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-20504 Filed 8-11-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

14 CFR Part 73

[Airspace Docket No. 00-AGL-21]

RIN 2120-AA66

Revocation of Restricted Area R-3302 Savanna; IL

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action removes Restricted Area 3302 (R-3302) Savanna, IL. The FAA is taking this action in response to a Department of Defense (DOD), United States Army (USA) determination that this restricted airspace is no longer required to support the USA mission.

EFFECTIVE DATE: 0901 UTC, October 5, 2000.

FOR FURTHER INFORMATION CONTACT: Bil Nelson, Airspace and Rules Division, ATA-400, Office of Air Traffic Airspace Management, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Background

The USA's position on special use airspace (SUA) is that they will keep and efficiently utilize only that airspace necessary to accomplish the mission of the USA. In keeping with that policy, the USA has closed the Savanna Army Depot. As a result, all military related operations have ceased at the depot, therefore, R-3302 is no longer required.

The Rule

This amendment to 14 CFR part 73 removes R-3302 Savanna, IL. The FAA is taking this action in response to a DOD, USA determination that this restricted airspace is no longer required to support the USA mission. Because this action only involves removal of restricted airspace, I find that notice and public comment under 5 U.S.C. 553(b) are unnecessary.

Section 73.33 of 14 CFR part 73 was republished in FAA Order 7400.8G, dated September 1, 1999.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

This action reduces restricted airspace. The rule contains no changes to air traffic control procedures or routes. Therefore, the FAA has determined that this action is not subject to environmental assessments and procedures in accordance with FAA Order 1050.1D, “Policies and Procedures for Considering Environmental Impacts,” and the National Environmental Policy Act.

List of Subjects on 14 CFR Part 73

Airspace, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 73 as follows:

PART 73—SPECIAL USE AIRSPACE

1. The authority citation for part 73 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 73.33 [Amended]

2. § 73.33 is amended as follows:

* * * * *

R-3302 Savanna, IL [Removed]

* * * * *

Issued in Washington, DC, on August 8, 2000.

Reginald C. Matthews,

Manager, Airspace and Rules Division.

[FR Doc. 00-20585 Filed 8-11-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF JUSTICE

Drug Enforcement Administration

21 CFR Part 1304

[DEA-143C]

RIN 1117-AA36

Establishment of Freight Forwarding Facilities for DEA Distributing Registrants

AGENCY: Drug Enforcement Administration (DEA), Justice.

ACTION: Final rule; correction.

SUMMARY: This document contains a correction to the final regulation which was published, on Wednesday, July 19, 2000 (65 FR 44674, rule document 00-18147). The regulation discussed the establishment of freight forwarding facilities for DEA distributing registrants.

EFFECTIVE DATE: August 14, 2000.