

PART 39—LICENSES AND RADIATION SAFETY REQUIREMENTS FOR WELL LOGGING

■ 14. The authority citation for Part 39 continues to read as follows:

Authority: Secs. 53, 57, 62, 63, 65, 69, 81, 82, 161, 182, 183, 186, 68 Stat. 929, 930, 932, 933, 934, 935, 948, 953, 954, 955, as amended, sec. 234, 83 Stat. 444, as amended (42 U.S.C. 2073, 2077, 2092, 2093, 2095, 2099, 2111, 2112, 2201, 2232, 2233, 2236, 2282); secs. 201, as amended, 202, 206, 88 Stat. 1242, as amended, 1244, 1246 (42 U.S.C. 5841, 5842, 5846).

■ 15. Section 39.55 is revised to read as follows:

§ 39.55 Tritium neutron generator target sources.

(a) Use of a tritium neutron generator target source, containing quantities not exceeding 1,110 GBq [30 curies] and in a well with a surface casing to protect fresh water aquifers, is subject to the requirements of this part except §§ 39.15, 39.41, and 39.77.

(b) Use of a tritium neutron generator target source, containing quantities exceeding 1,110 GBq [30 curies] or in a well without a surface casing to protect fresh water aquifers, is subject to the requirements of this part except § 39.41.

PART 40—DOMESTIC LICENSING OF SOURCE MATERIAL

■ 16. The authority citation for Part 40 continues to read as follows:

Authority: Secs. 62, 63, 64, 65, 81, 161, 182, 183, 186, 68 Stat. 932, 933, 935, 948, 953, 954, 955, as amended, secs. 11e(2), 83, 84, Pub. L. 95–604, 92 Stat. 3033, as amended, 3039, sec. 234, 83 Stat. 444, as amended (42 U.S.C. 2014(e)(2), 2092, 2093, 2094, 2095, 2111, 2113, 2114, 2201, 2232, 2233, 2236, 2282); sec. 274, Pub. L. 86–373, 73 Stat. 688 (42 U.S.C. 2021); secs. 201, as amended, 202, 206, 88 Stat. 1242, as amended, 1244, 1246 (42 U.S.C. 5841, 5842, 5846); sec. 275, 92 Stat. 3021, as amended by Pub. L. 97–415, 96 Stat. 2067 (42 U.S.C. 2022); sec. 193, 104 Stat. 2835, as amended by Pub. L. 104–134, 110 Stat. 1321, 1321–349 (42 U.S.C. 2243).

Section 40.7 also issued under Pub. L. 95–601, sec. 10, 92 Stat. 2951 (42 U.S.C. 5851). Section 40.31(g) also issued under sec. 122, 68 Stat. 939 (42 U.S.C. 2152). Section 40.46 also issued under sec. 184, 68 Stat. 954, as amended (42 U.S.C. 2234). Section 40.71 also issued under sec. 187, 68 Stat. 955 (42 U.S.C. 2237).

■ 17. In § 40.42, paragraph (l) is revised to read as follows:

§ 40.42 Expiration and termination of licenses and decommissioning of sites and separate buildings or outdoor areas.

* * * * *

(l) Specific licenses for uranium and thorium milling are exempt from

paragraphs (d)(4), (g) and (h) of this section with respect to reclamation of tailings impoundments and/or waste disposal areas.

PART 50—DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

■ 18. The authority citation for Part 50 continues to read as follows:

Authority: Secs. 102, 103, 104, 105, 161, 182, 183, 186, 189, 68 Stat. 936, 937, 938, 948, 953, 954, 955, 956, as amended, sec. 234, 83 Stat. 444, as amended (42 U.S.C. 2132, 2133, 2134, 2135, 2201, 2232, 2233, 2236, 2239, 2282); secs. 201, as amended, 202, 206, 88 Stat. 1242, as amended, 1244, 1246 (42 U.S.C. 5841, 5842, 5846).

Section 50.7 also issued under Pub. L. 95–601, sec. 10, 92 Stat. 2951 (42 U.S.C. 5841). Section 50.10 also issued under secs. 101, 185, 68 Stat. 955, as amended (42 U.S.C. 2131, 2235); sec. 102, Pub. L. 91–190, 83 Stat. 853 (42 U.S.C. 4332). Sections 50.13, 50.54(D.D.), and 50.103 also issued under sec. 108, 68 Stat. 939, as amended (42 U.S.C. 2138). Sections 50.23, 50.35, 50.55, and 50.56 also issued under sec. 185, 68 Stat. 955 (42 U.S.C. 2235). Sections 50.33a, 50.55a and Appendix Q also issued under sec. 102, Pub. L. 91–190, 83 Stat. 853 (42 U.S.C. 4332). Sections 50.34 and 50.54 also issued under sec. 204, 88 Stat. 1245 (42 U.S.C. 5844). Sections 50.58, 50.91, and 50.92 also issued under Pub. L. 97–415, 96 Stat. 2073 (42 U.S.C. 2239). Section 50.78 also issued under sec. 122, 68 Stat. 939 (42 U.S.C. 2152). Sections 50.80–50.81 also issued under sec. 184, 68 Stat. 954, as amended (42 U.S.C. 2234). Appendix F also issued under sec. 187, 68 Stat. 955 (42 U.S.C. 2237).

■ 19. In Appendix H to Part 50, in the Introduction, the first sentence of the second paragraph is revised to read as follows:

Appendix H to Part 50—Reactor Vessel Material Surveillance Requirements

I. Introduction

* * * * *

ASTM E 185–73, “Standard Recommended Practice for Surveillance Tests for Nuclear Reactor Vessels”; ASTM E 185–79, “Standard Practice for Conducting Surveillance Tests for Light-Water Cooled Nuclear Power Reactor Vessels”; and ASTM E 185–82, “Standard Practice for Conducting Surveillance Tests for Light-Water Cooled Nuclear Power Reactor Vessels”; which are referenced in the following paragraphs, have been approved for incorporation by reference by the Director of the Federal Register. * * *

* * * * *

Dated at Rockville, Maryland this 22nd day of December, 2003.

For the Nuclear Regulatory Commission,
Michael T. Lesar,
Division of Administrative Services, Office
of Administration.

[FR Doc. 03–31952 Filed 12–30–03; 8:45 am]

BILLING CODE 7590–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Parts 23 and 33

[Docket No. FAA–1998–4815; Amendment No. 23–54 and 33–20]

RIN 2120–AF84

Airworthiness Standards; Bird Ingestion; Correction

AGENCY: Federal Aviation Administration, Transportation.

ACTION: Correcting amendments.

SUMMARY: This document contains corrections to the final regulations for bird ingestion type certification standards that the Federal Aviation Administration (FAA) published in the *Federal Register* on September 14, 2000 (65 FR 55848), with an effective date of December 13, 2000. These regulations revised the bird ingestion type certification standards for aircraft turbine engines.

DATES: Effective on January 1, 2004.

FOR FURTHER INFORMATION CONTACT: Marc Bouthillier, Engine and Propeller Standards Staff, ANE–110, Engine and Propeller Directorate, Aircraft Certification Service, Federal Aviation Administration (FAA), New England Region, 12 New England Executive Park, Burlington, Massachusetts 01803–5299; telephone (781) 238–7114; fax (781) 238–7199; electronic mail: Marc.bouthillier@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The final regulations that are the subject of these corrections, revised the bird ingestion type certification standards for aircraft turbine engines to better address the actual bird threat encountered in service, and established nearly uniform bird ingestion standards for aircraft turbine engines certified by the United States under FAA standards and by the Joint Aviation Authorities (JAA) countries under JAA standards, thereby simplifying airworthiness approvals for import and export.

Need for Correction

As published, the final regulations contain errors that may prove to be misleading and need to be clarified.

List of Subjects

14 CFR Part 23

Air transportation, Aircraft, Aviation safety, Safety.

14 CFR Part 33

Air transportation, Aircraft, Aviation safety, Safety.

■ Accordingly, 14 CFR parts 23 and 33 is corrected by making the following correcting amendments:

PART 23—AIRWORTHINESS STANDARDS: NORMAL, UTILITY, ACROBATIC, AND COMMUTER CATEGORY AIRPLANES

■ 1. The authority citation for part 23 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701, 44702, 44704.

■ 2. Correct paragraph (a)(2)(i) of § 23.903 to read as follows:

§ 23.903 [Corrected]

(a) In paragraph (a)(2)(i), the sentence should read “Sections 33.76, 33.77 and 33.78 of this chapter in effect on December 13, 2000, or as subsequently amended; or”.

PART 33—AIRWORTHINESS STANDARDS; AIRCRAFT ENGINES

■ 3. The authority citation for part 33 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701, 44702, 44704.

■ 4. Correct paragraphs (b)(1), (c)(1), (c)(7)(ii), (c)(7)(iii), (c)(7)(viii), (c)(7)(i)(x), (c)(8)(v), (c)(8)(v)(i), Table 1 and Table 2 of § 33.76 to read as follows:

§ 33.76 [Corrected]

1. In § 33.76, paragraph (b)(1), in two instances in this sentence, remove the word “rotocraft” and add in its place the word “rotorcraft”.

2. In § 33.76, in paragraph (c)(1), in the second sentence, remove the word “affects” and add in its place the word “effects” and remove the word “roto” and add in its place the word “rotor”.

3. In § 33.76, in paragraph (c)(7)(ii), remove the word “level” and add in its place the word “lever”.

4. In § 33.76, in paragraph (c)(7)(iii), remove the figure “175-percent” and add in its place the figure “75-percent”.

5. In § 33.76, in paragraph (c)(7)(viii), remove the sentence “The durations specified are times at the defined conditions with the power lever being moved between each condition in less than 10 seconds.”

6. In § 33.76, in paragraph (c)(7), add a new paragraph (c)(7)(ix) to read as follows:

* * * * *

(c) * * *

(7) * * *

(ix) The durations specified are times at the defined conditions with the

power being changed between each condition in less than 10 seconds.

* * * * *

7. In § 33.76, in paragraph (c)(8)(v), remove the sentence “The duration specified are times at the defined conditions with the power being changed between each condition in less than 10 seconds.”

8. In § 33.76, in paragraph (c)(8), add a new paragraph (c)(8)(vi) to read as follows:

* * * * *

(c) * * *

(8) * * *

(vi) The durations specified are times at the defined conditions with the power being changed between each condition in less than 10 seconds.

* * * * *

9. In § 33.76, in Table 1, in the first column heading, remove the words “Square/meters” and add in their place the words “Square-meters”.

10. In § 33.76, in Table 1, in the first column, second row, remove the figure “(2,029)” and add in its place “(2,092)”.

11. In § 33.76, in Table 2, in the first column, second row, remove the figure “.05” and add in its place “.05”.

12. In § 33.76, in Table 2, in the third column, tenth row, remove the figure “(2,53)” and add in its place “(2.53)”.

Issued in Burlington, Massachusetts, on December 18, 2003.

Peter A. White,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 03–32085 Filed 12–30–03; 8:45 am]

BILLING CODE 4910–13–M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003–CE–31–AD; Amendment 39–13403; AD 2003–26–06]

RIN 2120–AA64

Airworthiness Directives; Anjou Aeronautique Safety Belts and Restraint Systems

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA adopts a new airworthiness directive (AD) for certain Anjou Aeronautique (ANJOU) (formerly TRW Repa S.A., formerly L’AIGLON) safety belts and restraint systems that are installed in aircraft. This AD requires you to inspect safety belts and restraint systems for defects and service life limits, and, if necessary, repair

safety belts and restraint systems that have not reached service life limits; and replace safety belts and restraint systems that have reached service life limits. This AD is the result of reports of inadvertent unbuckling of the ANJOU seat belts and two safety recommendations to take AD action. We are issuing this AD to detect and correct defective safety belts and restraint systems, which could result in failure of the safety belts and restraint systems. This failure could lead to lack of occupant restraint during normal or crash loads.

DATES: This AD becomes effective on February 17, 2004.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulation as of February 17, 2004.

ADDRESSES: You may get the service information identified in this AD from Anjou Aeronautique, 13 Avenue De L’Osier, 49125 Tierce, France; telephone: 33 0 2 41 42 88 92; facsimile: 33 0 2 41 42 15 77.

You may view the AD docket at FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003–CE–31–AD, 901 Locust, Room 506, Kansas City, Missouri 64106. Office hours are 8 a.m. to 4 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4146; facsimile: (816) 329–4090.

SUPPLEMENTARY INFORMATION:

Discussion

What Events Have Caused This AD?

The FAA issued Special Airworthiness Information Bulletin (SAIB) Number CE–02–44, dated September 4, 2002, for SOCATA—Groupe AEROSPATIALE (SOCATA) Model TBM 700 airplanes, concerning ANJOU seat belts. At that time, FAA did not make a determination of an unsafe condition and take AD action.

Later, FAA issued SAIB Number CE–03–06, dated November 7, 2002, for SOCATA Rallye 150T, Rallye 150ST, Rallye 235E, and Rallye 235C airplanes, concerning ANJOU seat belts. Again, FAA then did not make a determination of an unsafe condition and take AD action.

We continued to receive field reports of inadvertent unbuckling of the ANJOU seat belts. The FAA received two safety recommendations to take AD action (NPRM) to propose to require replacement of certain safety belts and restraint systems.