

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Short Brothers PLC: Docket 98–NM–138–AD.

Applicability: All Model SD3–60 SHERPA series airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct corrosion of the distance piece and adjacent side plates of the fuselage wing strut pick-up of the left and right stub wings, which could result in reduced strength of the wing strut attachment to the stub wing on the fuselage, and consequent reduced structural integrity of the main wing, accomplish the following:

(a) Within 90 days after the effective date of this AD, clean the pockets in the horizontal and vertical legs of the distance piece and adjacent faces of the side plates at the wing strut pick-up area on the stub wing, and perform a visual inspection to detect corrosion; in accordance with Shorts Service Bulletin SD3–60 SHERPA–53–2, dated November 4, 1997.

(b) If no corrosion is detected during the inspection required by paragraph (a) of this AD, prior to further flight, apply additional corrosion protection treatment in accordance with Shorts Service Bulletin SD3–60 SHERPA–53–2, dated November 4, 1997.

(c) If any corrosion is detected, prior to further flight, after cleaning and removing the corrosion from the distance piece and side plates in accordance with Shorts Service Bulletin SD3–60 SHERPA–53–2, dated

November 4, 1997, accomplish paragraph (c)(1) or (c)(2) of this AD, as applicable.

(1) If the depth of corrosion is within the limits specified in the service bulletin, apply additional corrosion protection treatment in accordance with the service bulletin.

(2) If the depth of corrosion is outside the limits specified in the service bulletin, accomplish either paragraph (c)(2)(i) or (c)(2)(ii) of this AD. Thereafter, repeat the detailed visual inspection required by paragraph (a) of this AD at intervals not to exceed 600 hours time-in-service or 90 days, whichever occurs first.

(i) Rework the damaged components in accordance with a method approved by either the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate; or the Civil Aviation Authority of the United Kingdom (or its delegated agent). Thereafter, repeat the detailed visual inspection required by paragraph (a) of this AD at intervals not to exceed 600 hours time-in-service or 90 days, whichever occurs first.

(ii) Replace the damaged components with new components in accordance with Shorts SD3–60 Sherpa Maintenance Programme Manual, Section 5–26–57, page 9, dated July 17, 1995.

(d) Within 10 days after accomplishing the initial cleaning and inspection required by paragraph (a) of this AD, submit a report of the inspection results (both positive and negative findings) to Short Brothers, PLC. Information collection requirements contained in this regulation have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120–0056.

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM–116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM–116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM–116.

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in British airworthiness directive 004–11–97.

Issued in Renton, Washington, on July 31, 1998.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98–21103 Filed 8–6–98; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Airspace Docket No. 98–ASO–9]

Proposed Establishment of Class E Airspace; Villa Rica, GA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice proposes to establish Class E airspace at Villa Rica, GA. A Global Positioning System (GPS) Runway (RWY) 10 Standard Instrument Approach Procedure (SIAP) has been developed for Stockmar Airport. As a result, controlled airspace extending upward from 700 feet Above Ground Level (AGL) is needed to accommodate the SIAP and for Instrument Flight Rules (IFR) operations at Stockmar Airport. The operating status of the airport will change from Visual Flight Rules (VFR) to include IFR operations concurrent with the publication of the SIAP.

DATES: Comments must be received on or before September 8, 1998.

ADDRESSES: Send comments on the proposal in triplicate to: Federal Aviation Administration, Docket No. 98–ASO–9, Manager, Airspace Branch, ASO–520, P.O. Box 20636, Atlanta, Georgia 30320.

The official docket may be examined in the Office of the Regional Counsel for Southern Region, Room 550, 1701 Columbia Avenue, College Park, Georgia 30337, telephone (404) 305–5586.

FOR FURTHER INFORMATION CONTACT: Nancy B. Shelton, Manager, Airspace Branch, Air Traffic Division, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305–5586.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views or arguments as they may desire. Comments that provide for factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify the airspace docket number and be submitted in triplicate to the address

listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Airspace Docket No. 98-ASO-9." The postcard will be date/time stamped and returned to the commenter. All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. All comments submitted will be available for examination in the Office of the Regional Counsel for Southern Region, Room 550, 1701 Columbia Avenue, College Park, Georgia 30337, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Federal Aviation Administration, Manager, Airspace Branch, ASO-520, Air Traffic Division, P.O. Box 20636, Atlanta, Georgia 30320. Communications must identify the notice number of this NPRM. Persons interested in being placed on a mailing list for future NPRMs should also request a copy of Advisory Circular No. 11-2A which describes the application procedure.

The Proposal

The FAA is considering an amendment to part 71 of the Federal Aviation Regulations (14 CFR Part 71) to establish Class E airspace at Villa Rica, GA. A GPS RWY 10 SIAP has been developed for Stockmar Airport. As a result, controlled airspace extending upward from 700 feet AGL is needed to accommodate the SIAP and for IFR operations at Stockmar Airport. The operating status of the airport will change from VFR to include IFR operations concurrent with the publication of the SIAP. Class E airspace designations for airspace areas extending upward from 700 feet or more above the surface are published in Paragraph 6005 of FAA Order 7400.9E dated September 10, 1997, and effective September 16, 1997, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an

established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (Air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for Part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9E, Airspace Designations and Reporting Points, dated September 10, 1997, and effective September 16, 1997, is amended as follows:

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

ASO GA E5 Villa Rica, GA [New]

Stockmar Airport, GA
(Lat. 33°45'23"N, long 84°53'05"W)

That airspace extending upward from 700 feet or more above the surface of the earth within a 6.3-mile radius of Stockmar Airport.

* * * * *

Issued in College Park, Georgia, on June 10, 1998.

Nancy B. Shelton,

*Acting Manager, Air Traffic Division,
Southern Region.*

[FR Doc. 98-17857 Filed 8-6-98; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 98-AEA-15]

Proposed Amendment to Class E Airspace, Fort Drum, NY

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice proposes to amend the Class E airspace area at Fort Drum, NY. The development of Standard Instrument Approach Procedure (SIAP) based on the Global Positioning System (GPS) and Instrument Landing System (ILS) at Wheeler Sack Army Air Field (AAF) has made this proposal necessary. Additional controlled airspace extending upward from 700 feet Above Ground Level (AGL) is needed to accommodate these SIAPs and for Instrument Flight Rules (IFR) operations at the airport.

DATES: Comments must be received on or before September 8, 1998.

ADDRESSES: Send comments on the proposal in triplicate to: Manager, Airspace Branch, AEA-520, Docket No. 98-AEA-15, F.A.A. Eastern Region, Federal Building # 111, John F. Kennedy Int'l Airport, Jamaica, NY 11430.

The official docket may be examined in the Office of the Regional Counsel, AEA-7, F.A.A. Eastern Region, Federal Building # 111, John F. Kennedy International Airport, Jamaica, New York 11430. An informal docket may also be examined during normal business hours in the Airspace Branch, AEA-520, F.A.A. Eastern Region, Federal Building # 111, John F. Kennedy International Airport, Jamaica, NY 11430.

FOR FURTHER INFORMATION CONTACT: Mr. Francis T. Jordan, Jr., Airspace Specialist, Airspace Branch, AEA-520 F.A.A. Eastern Region, Federal Building # 111, John F. Kennedy International Airport, Jamaica, New York 11430; telephone (718) 553-4521.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments