

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent wear (scratches or grooving) of the aft upper fittings of the rear engine mount, and consequent reduced structural integrity of the engine mounts, accomplish the following:

(a) Within 10 months after the effective date of this AD, perform a one-time visual inspection of the stiffeners for the upper left and right engine cowls to ensure the stiffeners have the correct lower edge profile, in accordance with the Accomplishment Instructions of Avions de Transport Regional Service Bulletin ATR42-54-0019 or ATR72-54-1011, both dated March 9, 1998, as applicable.

(1) If the lower edge profile of the stiffener meets the specifications of the applicable service bulletin, no further action is required by this paragraph.

(2) If the lower edge profile of the stiffener does not meet the specifications of the applicable service bulletin, prior to further flight, modify or replace the stiffener with a new stiffener in accordance with the applicable service bulletin.

(b) Within 10 months after the effective date of this AD, perform a one-time detailed visual inspection for wear (scratches or grooving) of the aft upper fittings of the left- and right-hand rear engine mounts, in accordance with Avions de Transport Regional Service Bulletin ATR42-54-0019 (for Model ATR42 series airplanes) or ATR72-54-1011 (for Model ATR72 series airplanes), both dated March 9, 1998, as applicable.

(1) If no wear is detected, no further action is required by this paragraph.

(2) If any wear is detected that cannot be removed with a Type I or II blend-out as described in the applicable service bulletin, prior to further flight, repair in accordance with a method approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate.

(3) If any wear other than that specified in paragraph (b)(2) of this AD is detected, prior to further flight, repair in accordance with the Accomplishment Instructions of the applicable service bulletin.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116. Operators shall submit their requests through an appropriate FAA Principal Maintenance

Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(e) Except as provided by paragraph (b)(2) of this AD, the actions shall be done in accordance with Avions de Transport Regional Service Bulletin ATR42-54-0019, dated March 9, 1998, or Avions de Transport Regional Service Bulletin ATR72-54-1011, dated March 9, 1998, as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Aerospatiale, 316 Route de Bayonne, 31060 Toulouse, edex 03, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in French airworthiness directives 98-069-073(B) (for Model ATR42 series airplanes), dated February 11, 1998; and 98-071-035(B) (for Model ATR72 series airplanes), dated February 11, 1998, as revised by Erratum 98-071-35(B), dated February 25, 1998.

(f) This amendment becomes effective on September 11, 1998.

Issued in Renton, Washington, on July 31, 1998.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 98-21102 Filed 8-6-98; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 98-AEA-10]

Amendment to Class E Airspace; Dunkirk, NY

AGENCY: Federal Aviation Administration (FAA) DOT.

ACTION: Final rule.

SUMMARY: This action amends Class E airspace extending upward from 700 feet Above Ground Level (AGL) at Dunkirk, NY. The development of a Standard Instrument Approach Procedure (SIAP) based on the Global Positioning System (GPS) at Angola Airport, NY, has made this action necessary. This action is intended to

provide adequate Class E airspace to contain instrument flight rules (IFR) operations for aircraft executing the GPS Runway (RWY) 1 SIAP to Angola Airport.

EFFECTIVE DATE: 0901 UTC, October 8, 1998.

FOR FURTHER INFORMATION CONTACT: Mr. Francis Jordan, Airspace Specialist, Airspace Branch, AEA-520, Air Traffic Division, Eastern Region, Federal Aviation Administration, Federal Building #111, John F. Kennedy International Airport, Jamaica, New York 11430; telephone (718) 553-4521.

SUPPLEMENTARY INFORMATION:

History

On June 4, 1998, a proposal to amend Part 71 of the Federal Aviation Regulations (14 CFR Part 71) to amend the Class E airspace at Dunkirk, NY, was published in the **Federal Register** (63 FR 30428). The development of the GPS RWY 1 SIAP for Angola Airport, NY, requires the amendment of the Class E airspace at Dunkirk, NY. The proposal was to amend controlled airspace extending upward from 700 feet AGL to contain IFR operations in controlled airspace during portions of the terminal operation and while transitioning between the enroute and terminal environments.

Interested parties were invited to participate in this rulemaking proceeding by submitting written comments on the proposal to the FAA. No comments to the proposal were received. The rule is adopted as proposed.

The coordinates for this airspace docket are based on North American Datum 83. Class E airspace areas designations for airspace extending upward from 700 feet AGL are published in paragraph 6005 of FAA Order 7400.9E, dated September 10, 1997, and effective September 16, 1997, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

The Rule

This amendment to Part 71 of the Federal Aviation Regulations (14 CFR Part 71) amends Class E airspace at Dunkirk, NY, to provide controlled airspace extending upward from 700 feet AGL for aircraft executing the GPS RWY 1 SIAP to Angola Airport.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation—(1)

is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation it is certified that this rule will not have significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—[AMENDED]

1. The authority citation for 14 CFR Part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; EO 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9E, Airspace Designations and Reporting Points, dated September 10, 1997, and effective September 16, 1997, is amended as follows:

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

AEA NY E5 Dunkirk, NY [Revised]

Chautauqua County/Dunkirk Airport, NY
(Lat. 42° 29' 36" N., long. 79° 16' 19" W.)
Angola Airport, NY
(Lat 42° 39' 36" N., long. 78° 59' 28" W.)

That airspace extending upward from 700 feet above the surface within a 6.6-mile radius of Chautauqua County/Dunkirk Airport and within an 11.8-mile radius of the airport extending clockwise from a 022° to a 264° bearing from the airport and within a 6.3-mile radius of the Angola Airport and within 4 miles each side of the 179° bearing from the airport extending from the 6.3-mile radius to 10.5 miles south of the airport.

* * * * *

Issued in Jamaica, New York on July 29, 1998.

Franklin D. Hatfield,

Manager, Air Traffic Division, Eastern Region.
[FR Doc. 98–21180 Filed 8–6–98; 8:45 am]

BILLING CODE 4910–13–M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Amdt No. 1881; Docket No. 29293]

RIN 212–AH 65

Standard Instrument Approach Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This amendment establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, addition of new obstacles, or changes in air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: An effective date for each SIAP is specified in the amendatory provisions.

Incorporation by reference-approved by the Director of the Federal Register on December 31, 1980, and reapproved as of January 1, 1982.

ADDRESSES: Availability of matters incorporated by reference in the amendment is as follows:

For Examination-

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;

2. The FAA Regional Office of the region in which the affected airport is located; or

3. The Flight Inspection Area Office which originated the SIAP.

For Purchase- Individual SIAP copies may be obtained from:

1. FAA Public Inquiry Center (APA–200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or

2. The FAA Regional Office of the region in which the affected airport is located.

By Subscription- Copies of all SIAPs, mailed once every 2 weeks, are for sale by the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

FOR FURTHER INFORMATION CONTACT: Donald P. Pate, Flight Procedure

Standards Branch (AMCAFS–420), Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd. Oklahoma City, OK. 73169 (Mail Address: P.O. Box 25082 Oklahoma City, OK. 73125) telephone: (405) 954–4164.

SUPPLEMENTARY INFORMATION: This amendment to part 97 of the Federal Aviation Regulations (14 CFR part 97) establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs). The complete regulatory description of each SIAP is contained in official FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and § 97.20 of the Federal Aviation Regulations (FAR). The applicable FAA Forms are identified as FAA Forms 8260–3, 8260–4, and 8260–5. Materials incorporated by reference are available for examination or purchase as stated above.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unnecessary. The provisions of this amendment state the affected CFR (and FAR) sections, with the types and effective dates of the SIAPs. This amendment also identifies the airport, its location, the procedure identification and the amendment number.

The rule

This amendment to part 97 is effective upon publication of each separate SIAP as contained in the transmittal. Some SIAP amendments may have been previously issued by the FAA in a National Flight Data Center (NFDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for some SIAP amendments may require making them effective in less than 30 days. For the remaining SIAPs, an effective date at least 30 days after publication is provided.

Further, the SIAPs contained in this amendment are based on the criteria contained in the U.S. Standard for